

## Measuring

humidistat



- Controls humidity or temperature
- Microprocessor controlled.
- EPROM Memory
- External humidity sensor.
- Connection length to sensor box up to 100 meters.
- Monitoring and setting of humidity is 5-95 % RH
- Accuracy of measurement  $\pm 3\%$  RH
- 1 ON/OFF output to control a humidifier

Pressure switch



Pressure regulator




High pressure gauge (160 bar)



Low pressure gauge (10 bar)




## Flexible nozzle extension adaptor



## Control boxes

### CONTROL BOXES FOR MISTING PUMPS

PART NO	PART NAME	PUMPS	MOTOR PROTECTION	PUMP PROTECTION	HUMIDISTAT INPUT	HOUR METER	TIMER	STAR TRIANGLE	HUMIDISTAT	AUTO DRAIN	REMOTE CONTROL	WEIGHT Kg	DIMENSION mm
1	0204001-6	PSS 6A	*	*	*	*	*	*	*	*	OPTION	8,0	300x350x170
2	0204002-6	PSS 6A/O	*	*	*	*	*	*	*	*	OPTION	8,3	300x350x170
3	0204001-12	PSS12A	*	*	*	*	*	*	*	*	OPTION	8,0	300x350x170
4	0204002-12	PSS12A/O	*	*	*	*	*	*	*	*	OPTION	8,3	300x350x170
5	0204002-12H	PSS12A/OH	*	*	*	*	*	*	*	*	*	10,2	300x400x180
6	0204003	PST12A	*	*	*	*	*	*	*	*	OPTION	9,4	300x400x180
7	0204004	PST12A/O	*	*	*	*	*	*	*	*	OPTION	9,7	300x400x180
8	0204004H	PST12A/OH	*	*	*	*	*	*	*	*	*	10,5	300x400x180
9	0204007	PST20A	*	*	*	*	*	*	*	*	OPTION	12,1	350x450x180
10	0204008	PST20A/O	*	*	*	*	*	*	*	*	OPTION	12,3	350x450x180
11	0204008H	PST20A/OH	*	*	*	*	*	*	*	*	*	14,0	350x450x180
12	SPECIAL 1	FOR HUMIDITY KIT	*	*	*	*	*	*	*	*	-	8,5	300x350x170
13	BLUE SPECIAL 2	KJ4C - KJ8C	*	*	*	*	*	*	*	*	*	10,4	300x400x180



1 / 3      2 / 4      5      6 / 9      7 / 10      8 / 11      12      13